

Inspection Photo (s)
GMR 21-8D
API # 05-045-09285
Inspection # 689303118



Location Photo #1



Location Photo #2

Inspection Photo (s)
GMR 21-8D
API # 05-045-09285
Inspection # 689303118



Location Photo #3, Hole in secondary containment liner.



Location Photo #4, Hole in secondary containment liner.

Inspection Photo (s)
GMR 21-8D
API # 05-045-09285
Inspection # 689303118



**Location Photo #5, Hole in secondary
containment liner.**