

**Inspection Photo (s)**  
**GMR 21-10B**  
**API # 05-045-08195**  
**Inspection # 689303120**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**GMR 21-10B**  
**API # 05-045-08195**  
**Inspection # 689303120**



**Location Photo #3, unmarked, unused flowline riser.**



**Location Photo #4, unused equipment next to separator.**