

**Inspection Photo (s)**  
**GMR 28-2A**  
**API # 05-045-09838**  
**Inspection # 689303124**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**GMR 28-2A**  
**API # 05-045-09838**  
**Inspection # 689303124**



**Location Photo #3, Stained soil. Mechanical integrity of valves.**

**Location Photo #4, stained material.**