

**Inspection Photo (s)**  
**GMU 33-6**  
**API # 05-045-10829**  
**Inspection # 689303126**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo (s)**  
**GMU 33-6**  
**API # 05-045-10829**  
**Inspection # 689303126**



**Location Photo #3**



**Location Photo #4, Unmarked flowline risers.**

**Inspection Photo (s)**  
**GMU 33-6**  
**API # 05-045-10829**  
**Inspection # 689303126**



**Location Photo #5, unmarked flowline risers.**

**Location Photo #6, unmarked flowline risers.**