

Inspection Photo (s)
GMR 34-10A
API # 05-045-17578
Inspection # 689303128



Location Photo #1



Location Photo #2

Inspection Photo (s)
GMR 34-10A
API # 05-045-17578
Inspection # 689303128



Location Photo #3



Location Photo #4, 3 Unmarked flowline risers.

Inspection Photo (s)
GMR 34-10A
API # 05-045-17578
Inspection # 689303128



Location Photo #5, Stained material in battery containment.



Location Photo #6, Stained rock at blowdown line from separator.

**Inspection Photo (s)
GMR 34-10A
API # 05-045-17578
Inspection # 689303128**



Location Photo #7, Stained rock on North end of Vertical Separators.



Location Photo #8, Stained rock on North end of Vertical Separators.

Inspection Photo (s)
GMR 34-10A
API # 05-045-17578
Inspection # 689303128



Location Photo #9, Mechanical condition of tank valve. Stained rock below valve.



Location Photo #10, Stained material in battery containment.