

Inspection Photos 1/30/19
Location: Norbert Samford #1
API # 001-07140



Great Western signage and wellhead.



Flowline on ground surface running NW to battery

Inspection Photos 1/30/19
Location: Norbert Samford #1
API # 001-07140



View of flowline adjacent to lease road (looking SE toward wellhead).



Flowline tubing/ threaded connection; material is un coated. Note the impact on the steel from the pipe wrench.

Inspection Photos 1/30/19
Location: Norbert Samford #1
API # 001-07140



View of flowline on ground surface and adjacent residence to the south.



Flowline tie in at horizontal separator; also unused and unmarked flowline riser (incomplete abandonment); Riser is absent of lockout/ tagout.