

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/24/2019

Submitted Date:

01/25/2019

Document Number:

692601236**FIELD INSPECTION FORM**
 Loc ID 439638 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10594Name of Operator: L B EXPLORATION INCAddress: 2135 2ND ROADCity: HOLYROOD State: KS Zip: 67450**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Petermann, Michael	(785) 252-8034	lbexploration@hbcomm.net	
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439639	WELL	TA	03/01/2016	GW	099-06913	WOOTTEN 2-21-2246	TA

**General Comment:**Routine Inspection

**Location****Lease Road:**

Type	Access		
comment:	Trail through pasture		
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	Lease sign at entrance by county road		
Corrective Action:	Update lease sign to current operator	Date:	04/24/2019

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 439639 Type: WELL API Number: 099-06913 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Well is TA at time of inspection. No record of MIT in well file. Passing MIT is requiredCorrective Action: Well must have a successful mechanical integrity test performed or plugged as directed by Rule 319 b (3)  
Contact COGCC Engineering Group within 10 days of receipt of this inspectionDate: 02/03/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Location and access are grassed over with vegetation](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401918810	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715535">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715535</a>
692601237	Wooten 2-21-2246	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715533">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4715533</a>