

Location Name: Crow Creek State Production Facility Location ID: 432762 Inspection Date: 1/30/2019



Photo 1 – View trench in area of release, looking south. Stained soil can be seen in eastern sidewall, and in preferential flow toward west and surface where release was discovered. Lateral piping entering trench is unused piping installed for future production. Main line piping are from east to west (left to right in photo): abandoned water line, 2"-diameter active water line, 6" active produced fluids line (suspected release source), 8" active gas line, 2" water line.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Crow Creek State Production Facility Location ID: 432762 Inspection Date: 1/30/2019



Photo 2 – View trench in area of release, looking south. Stained soil can be seen in eastern sidewall, and in preferential flow toward west and surface where release was discovered. Lateral piping entering trench is unused piping installed for future production. Main line piping are from east to west (left to right in photo): abandoned water line, 2"-diameter active water line, 6" active produced fluids line (suspected release source), 8" active gas line, 2" water line.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources