

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/18/2019

Submitted Date:

01/18/2019

Document Number:

695100058**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 308594      Beardslee, Tom      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10672Name of Operator: TIMBER CREEK OPERATING LLCAddress: 1001 17TH STREET #1000City: DENVER      State: CO      Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name       | Phone                     | Email                        | Comment         |
|--------------------|---------------------------|------------------------------|-----------------|
| Pesicka, Conor     |                           | conor.pesicka@state.co.us    |                 |
| Amato, Joseph      | 719-845-2110/719-859-2263 | josephamato@tcenergy.us      | All Inspections |
| Kosola, Jason      |                           | jason.kosola@state.co.us     |                 |
| Labowskie, Steve   |                           | steve.labowskie@state.co.us  |                 |
| Santistevan, Vince | 719-845-2102/719-680-9705 | vincesantistevan@tcenergy.us | All Inspections |
| Gomez, Jason       |                           | jason.gomez@state.co.us      |                 |
| Ash, Margaret      |                           | margaret.ash@state.co.us     |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 275728      | WELL | PR     | 12/01/2010  | GW         | 071-08296 | APACHE CANYON 12-03 | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | OTHER                |       |  |
| Comment:             | location sign        |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | STAINED SOIL OUTSIDE OF COMPRESSOR SKID THAT APPEARS TO BE COMING FROM SCUBBER DRAIN. STAINED SOIL NEAR EXHAUST PIPE OF COMPRESSOR SKID. EXISTING HOLE NEAR COMPRESSOR SKID DRAIN PLUG APPEARS TO HAVE STAINED SOIL IN HOLE |       |            |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A. Contact COGCC EPS staff.   | Date: | 01/22/2019 |
| Type               | OTHER   |       |            |
| Comment:           | TBG HEAD PACKING LEAKING FLUID ONTO LOCATION  |       |            |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.   | Date: | 01/19/2019 |
| Type               | OTHER   |       |            |
| Comment:           | Materials handling and spill prevention procedures and practices.<br>Self-inspection, maintenance and good house keeping procedures and schedules.  |       |            |
| Corrective Action: | Comply with COGCC rule 1002 F (2) B<br>Comply with COGCC rule 1002 F (2) D Provide COGCC with pocedure and maintenance documentation within 48hrs   | Date: | 01/22/2019 |

Overall Good: ☐

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                   |  |  |                 |
|-------------------|--|--|-----------------|
| <b>Equipment:</b> |  |  | corrective date |
| Type: Compressor  | # 1  |  |                 |
| Comment:          | WELL APPEARS TO BE PRODUCED BY VACUUM. NO SUNDRY NOTICE ON RECORD. |  |                 |

|                    |                     |       |            |
|--------------------|---------------------|-------|------------|
| Corrective Action: | COMPY WITH RULE 331 | Date: | 02/18/2019 |
|--------------------|---------------------|-------|------------|

**Tanks and Berms:**

| Contents       | # | Capacity | Type      | Tank ID | SE GPS                |
|----------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <50 BBLs | STEEL AST |         | 37.105030,-104.949250 |

|                    |       |
|--------------------|-------|
| Comment:           |       |
| Corrective Action: | Date: |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) | 30 BBL   |
| Other (Type)     |          |

**Berms**

| Type  | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|-------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |

|                    |                          |
|--------------------|--------------------------|
| Comment:           | BERM IS METAL STOCK TANK |
| Corrective Action: | Date:                    |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**Facility ID: 275728 Type: WELL API Number: 071-08296 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**BradenHead**Comment: PLUMBED TO SURFACE

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401911105    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708017">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708017</a> |
| 695100059    | LOC PICS             | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4708008</a> |