

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2019

Submitted Date:

02/04/2019

Document Number:

689303138**FIELD INSPECTION FORM**

Loc ID 335239 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:19 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300230	WELL	PR	05/21/2012	GW	045-17866	JOLLEY KP 332-17	PR
300231	WELL	PR	08/26/2016	GW	045-17865	JOLLEY KP 32-17	PR
300232	WELL	PR	04/01/2012	GW	045-17864	JOLLEY KP 432-17	PR
300334	WELL	PR	04/01/2012	GW	045-17893	JOLLEY KP 531-17	PR
300335	WELL	PR	04/01/2012	GW	045-17894	JOLLEY KP 542-17	PR
300336	WELL	PR	08/05/2016	GW	045-17895	JOLLEY KP 442-17	PR
300337	WELL	PR	04/01/2012	GW	045-17896	JOLLEY KP 342-17	PR
300338	WELL	PR	04/01/2012	GW	045-17897	JOLLEY KP 42-17	PR
300339	WELL	PR	05/21/2012	GW	045-17898	JOLLEY KP 541-17	PR

General Comment:

[Follow-up inspection from FIR DOC 689302662 in response to FIRR DOC 401893137. Corrective actions have not been completed.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-970-285-9377

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Unmarked flow line. see photo		
Corrective Action:	Comply with Rule 603.f .	Date:	01/17/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 9		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 9		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 12		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	2 chemical units at wellheads. 1 chemical unit at meter runs.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLs	STEEL AST		,	
Comment:	2 tanks are heated. 6 tanks in centralized containment.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	300230	Type:	WELL	API Number:	045-17866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300231	Type:	WELL	API Number:	045-17865	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300232	Type:	WELL	API Number:	045-17864	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300334	Type:	WELL	API Number:	045-17893	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300335	Type:	WELL	API Number:	045-17894	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300336	Type:	WELL	API Number:	045-17895	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300337	Type:	WELL	API Number:	045-17896	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300338	Type:	WELL	API Number:	045-17897	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Facility ID:	300339	Type:	WELL	API Number:	045-17898	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303139	Inspection photo 689303139	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4723374