

## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



Colorado Oil & Gas Conservation Commission  
40.8901, -103.96853, 1568.0m, 109°  
2018/09/20 11:31:49 AM

**Photo #1**

**Dolan Ranches 13-27 (API # 05-123-07364) Wellhead**

**Bradenhead does NOT appear plumbed to surface**

**Weeds**

*from prev. FIR*



Colorado Oil & Gas Conservation Commission  
40.8902, -103.96851, 1566.0m, 110°  
2019/02/04 11:08:58 AM

**Photo #2**

**Dolan Ranches 13-27 Wellhead**

**Bradenhead does NOT appear plumbed to surface**

**Weeds**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #3**

**Dolan Ranches 13-27** Battery

**Weeds**

*from prev. FIR*



**Photo #4**

**Dolan Ranches 13-27** Battery

**Weeds**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #5**

**Dolan Ranches 13-27** Crude oil tanks area

**Battery sign**

**Weeds**

*from prev. FIR*



**Photo #6**

**Dolan Ranches 13-27** Crude oil tanks area

**Battery sign**

**Weeds**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #7**

**Dolan Ranches 13-27** Crude oil tanks area  
Tanks have been removed. Piping remains  
**Unused Equipment | Uncapped piping**  
*from prev. FIR*



**Photo #8**

**Dolan Ranches 13-27** Crude oil tanks area  
Tanks have been removed. Piping remains  
**Unused Equipment | Uncapped piping**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #9**

**Dolan Ranches 13-27** Treater area  
Treater removed. Piping remains  
Unused Equipment | Stained soil  
*from prev. FIR*



**Photo #10**

**Dolan Ranches 13-27** Treater area  
Treater removed. Piping remains  
**Unused Equipment | Stained soil**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #11**

**Dolan Ranches 13-27** Treater area

**Stained Soil**

*from prev. FIR*



**Photo #12**

**Dolan Ranches 13-27** Treater area

**Stained Soil**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



Colorado Oil & Gas Conservation Commission  
40.89006, -103.96833, 1563.0m, 285°  
2018/09/20 11:33:32 AM

**Photo #13**

**Dolan Ranches 13-27** Wellsite

Pumpjack area

**Weeds | Stained soil**

*from prev. FIR*



Colorado Oil & Gas Conservation Commission  
40.89007, -103.96838, 1568.0m, 300°  
2019/02/04 11:32:03 AM

**Photo #14**

**Dolan Ranches 13-27** Wellsite

Pumpjack area

**Weeds | Stained soil | Unused Equipment**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #15**

**Dolan Ranches 13-27 Wellsite**  
**Unused chemical drum & rack**  
**Trash & Debris**  
*from prev. FIR*



**Photo #16**

**Dolan Ranches 13-27 wellsite**  
**Unused chemical drum & rack**  
**Trash & Debris**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #17**

**Dolan Ranches 13-27** Wellsite

**Trash**

*from prev. FIR*



**Photo #18**

**Dolan Ranches 13-27** Wellsite

**Trash**



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #19**

**Dolan Ranches 13-27** Crude oil tanks area

**Open bucket of oily waste**

*from prev. FIR*



**Photo #20**

**Dolan Ranches 13-27** Crude oil tanks area

**Open bucket of oily waste**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #21**

**Dolan Ranches 13-27 Pit skim tank**

**No capacity or contents label**

**Stained soil | Weeds**

*from prev. FIR*



**Photo #22**

**Dolan Ranches 13-27 Pit skim tank**

**No capacity or contents label**

**Stained soil | Weeds**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #23**

**Dolan Ranches 13-27** Northeast pit

**Weeds | Damaged liner | Algae**

*from prev. FIR*



**Photo #24**

**Dolan Ranches 13-27** Northeast pit

**Weeds | Damaged liner**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



Colorado Oil & Gas Conservation Commission  
40.89036, -103.96823, 1573.0m, 333°  
2018/09/20 11:59:00 AM

**Photo #25**

**Dolan Ranches 13-27 Northwest pit**

**Weeds | Damaged liner | Algae**

*from prev. FIR*



Colorado Oil & Gas Conservation Commission  
40.89033, -103.96815, 1587.0m, 345°  
2019/02/04 11:44:50 AM

**Photo #26**

**Dolan Ranches 13-27 Northwest pit**

**Weeds | Damaged liner**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #27**

**Dolan Ranches 13-27 Southwest pit**

**Weeds | Damaged liner | Algae**

*from prev. FIR*



**Photo #28**

**Dolan Ranches 13-27 Southwest pit**

**Weeds | Damaged liner**



## Inspection Photos

Location Name: DOLAN RANCHES-611N59W /27SWSW

Location #: 317614



**Photo #29**

**Dolan Ranches 13-27** Access road

**Severe erosion | No BMP**

*from prev. FIR*



**Photo #30**

**Dolan Ranches 13-27** Access road

**Severe erosion | No BMP**



## Inspection Photos

**Location Name:** DOLAN RANCHES-611N59W /27SWSW

**Location #:** 317614



**Photo #31**

**Dolan Ranches 13-27**

**Unmarked riser w/ closed valve**

**NOT LOTO**

*SW of wellsite*

