

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/29/2019

Submitted Date:

01/29/2019

Document Number:

675001852**FIELD INSPECTION FORM**
 Loc ID 312507 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num:           
**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	<a href="#">Petroleum Engineer</a>
,		aak2@kahnjeeholding.com	<a href="#">All Inspections</a>
Ried, Jordan	970-563-400	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Graves, Jim		mrinc20@qwestoffice.net	
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221808	WELL	SI	06/12/1983	GW	077-08410	FEDERAL 25-3	SI

**General Comment:**

This is a follow up inspection to FIR Doc#689401238 dated 5/17/18. Any corrective actions not addressed from previous inspections are still applicable.

This well is included in the AOC # 1V-609.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Access road is not being maintained		
Corrective Action	Repair and maintain lease road to comply with rule 204.	Date:	03/04/2019

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-970-585-8550

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Risers have been disconnected, marked with spray paint Meter run has been removed complying with previous inspection dated 5/17/18		
Corrective Action:	Comply with Rule 603.f .	Date:	03/04/2019

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 221808 Type: WELL API Number: 077-08410 Status: SI Insp. Status: SI**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Shut in All surface equipmet has been removed except some risers and the wellheadNo current Form 4 on file for continued TA status. According to AOC 1V-609 order #11 annual submission is still required  
. I find no evidence of this form filedCorrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.Date: 06/18/2018  
Inspected Facilities  
DateDate: 06/18/2018

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Gravel						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Shut in All surface equipmet has been removed except some risers and the wellhead This well is included in the AOC # 1V-609.	wentzeld	01/29/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401922487	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4718634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4718634</a>
675001860	Inspection 675001852 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4718628">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4718628</a>