

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

687903677

**FIELD INSPECTION FORM**

Loc ID 311887 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10464  
Name of Operator: CATAMOUNT ENERGY PARTNERS LLC  
Address: 1801 BROADWAY #1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 10 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Fischer, Reed	720-484-2346	Inspections@catamountep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216304	WELL	PR	07/01/2011	GW	067-07910	F W TERRELL GAS UNIT 2	PR
296161	WELL	PR	06/19/2018	GW	067-09559	IGW 122	PR

**General Comment:**

Conducted inspection with SW FIU Steve Labowskie. Downloadable photos are at the end of this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Metal framed sign at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(970) 442-6620. Correct contact info.	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	TRASH		
Comment:	Oily rags and used parts on pump jack skid.		
Corrective Action:	Comply with Rule 603.f.	Date:	02/11/2019
Type	UNUSED EQUIPMENT		
Comment:	Metal building with unused equipment.		
Corrective Action:	Remove unused equipment per Rule 603.f. Allowing for extra time to comply with CA due to weather conditions and the time of year.		Date: 05/30/2019

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Horizontal Heated Separator	#		
Comment:			
Corrective Action:		Date:	
Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Ancillary equipment	# 2		
Comment:	Wellhead, bradenhead inspection ports.		
Corrective Action:		Date:	
Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLs	STEEL AST		
Comment: <a href="#">Leaking valve and broken plastic plug on IGW 122 tank.</a>					
Corrective Action: <a href="#">Make necessary repairs per Rule 605.d</a>					Date: <a href="#">01/31/2019</a>

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Tires in secondary containment. Tires are trash.</a>				
Corrective Action: <a href="#">Clean up trash per Rule 603.f</a>				Date: <a href="#">02/11/2019</a>

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 216304 Type: WELL API Number: 067-07910 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 296161 Type: WELL API Number: 067-09559 Status: PR Insp. Status: PR**Producing Well**

Comment:

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401923270	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719445">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719445</a>
687903678	Well Sign.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719427">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719427</a>
687903679	Tires in Containment.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719428">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719428</a>
687903680	Leaking valve, broken cap.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719429">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719429</a>
687903681	Metal Building.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719430">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719430</a>
687903682	Unused Equipment in shed.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719431">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719431</a>