

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

687903691**FIELD INSPECTION FORM**

Loc ID 311924 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216305	WELL	PR	09/01/2017	GW	067-07911	OLSON-SMITH GAS UNIT 2	PR
295725	WELL	PR	09/12/2017	GW	067-09545	IGE 127	PR

General Comment:

[Conducted inspection with SW FIU Supervisor Steve Labowskie. Downloadable pictures at end of inspection report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Framed metal sign.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Emergency contact up to date. (970) 442-6620
Corrective Action:	Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	Trash and rags on pump jack skid.		
Corrective Action:	Clean up trash to comply with Rule 603.f.	Date:	02/11/2019

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:	Pump jack has gearbox leak and a slight puddle on concrete base.		
Corrective Action:	Repair equipment as necessary to comply with rule 605.d and Rule 907.e.	Date:	02/08/2019
Type: Ancillary equipment	# 2		
Comment:	wellhead stuffing box leak.		
Corrective Action:	Repair leak to comply with Rule 605.d.	Date:	02/01/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:	Thief hatch found open at time of inspection.				
Corrective Action:	Comply with Rule 605.d.				Date: 02/28/2019

Paint

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Sufficient	Inadequate
Comment:	<p>Large tear in southern wall secondary containment.</p> <p>Tires in secondary containment.</p>			
Corrective Action:	<p>Repair or replace damaged liner per Rule 605.a.(4).</p> <p>Remove trash to comply with Rule 603.f.</p>			<p>Date: 02/28/2019</p>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 216305 Type: WELL API Number: 067-07911 Status: PR Insp. Status: PRFacility ID: 295725 Type: WELL API Number: 067-09545 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401923273	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719448
687903692	Stuffing box leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719438
687903693	Gear box leak	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719439
687903694	Gear box leak on concrete	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719440
687903695	Tires in secondary	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719441
687903696	Compromised liner tear	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4719442