

Inspection Photos
Location Name: PEOC-NVG 41-23H
API: 05-107-06173



Photo 1. Overview of location taken at entrance facing southeast.

Inspection Photos
Location Name: PEOC-NVG 41-23H
API: 05-107-06173



Photo 2. Staining on tank sides.



Photo 3. Staining on tank sides.