

Inspection Photos
Location Name: GENGHIS 44-16
API #: 05-071-06753
Insp. Doc. # 695100131



PHOTO 1: WELLHEAD



**PHOTO 2: WELL SIGN/METER HOUSE/SIGN NOT POSTED OR
INACCURATE INFORMATION/NO EMERGENCY CONTACT NUMBER**

Inspection Photos
Location Name: GENGHIS 44-16
API #: 05-071-06753
Insp. Doc. # 695100131



PHOTO 3: STANDING WATER ON TBG HEAD APPEARS TO HAVE LEAKING PACKING ON POLISH ROD



PHOTO 4: STANDING WATER NEXT TO WELLHEAD/ STAINED SOIL AROUND WELLHEAD APPEARS TO BE FROM LEAKING WATER AT POLISH ROD.

Inspection Photos
Location Name: GENGHIS 44-16
API #: 05-071-06753
Insp. Doc. # 695100131



PHOTO 5: APPEARS HYDRAULIC HOSE CONNECTION IS SEEPING



PHOTO 6: STAINED SOIL UNDER DRIVEHEAD NEXT TO WELLHEAD.

Inspection Photos
Location Name: GENGHIS 44-16
API #: 05-071-06753
Insp. Doc. # 695100131



PHOTO 7: STAINED SOIL NEXT TO ENGINE SKID AT EXHAUST PIT OUTLET.



PHOTO 8: STAINED SOIL IN FRONT OF ENGINE SKID.

Inspection Photos
Location Name: GENGHIS 44-16
API #: 05-071-06753
Insp. Doc. # 695100131



PHOTO 9: TRASH UNDER ENGINE SKID.



PHOTO 10: TRASH INSIDE ENGINE SKID.

Inspection Photos
Location Name: GENGHIS 44-16
API #: 05-071-06753
Insp. Doc. # 695100131



PHOTO 11: METER HOUSE CALIBRATION LOG.