

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

689303120**FIELD INSPECTION FORM**Loc ID 324196 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|---|---------------------------------|
| Murray, Richard | | g.richard.murray@state.co.us | Pipeline group |
| Rider, Lindsay | 970-285-2711 | cogcc.inspections@caerusoila ndgas.com | All Inspections |
| Pesicka, Conor | | conor.pesicka@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 264267 | WELL | PR | 12/16/2002 | GW | 045-08195 | GMR 21-10B(21) | PR |

General Comment:[Routine Field Inspection.](#)

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Snow packed. | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Emergency Contact Number: | | | | |
| Comment: | 1-800-791-7691 | | | |
| Corrective Action: | | | | Date: |
| Good Housekeeping: | | | | |
| Type | DEBRIS | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type | UNUSED EQUIPMENT | | | |
| Comment: | 1) unused pipe next to separator, see photo. 2) Unmarked, unused flowline riser, see photo. | | | |
| Corrective Action: | 1) Comply with 603.f. 2) Comply with 603.f., For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser | | | Date: 03/04/2019 |
| Type | TRASH | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: <input type="text"/> | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Concrete barriers. | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bird Protectors | # 1 | | | corrective date |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Plunger Lift | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Horizontal Heated Separator | # 1 | | | |

| | | | |
|---------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE | 1 | 300 BBLS | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 264267 | Type: | WELL | API Number: | 045-08195 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift. | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 401924230 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720313 |
| 689303121 | Inspection photo 689303121 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720307 |