

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2019

Submitted Date:

01/30/2019

Document Number:

689303128**FIELD INSPECTION FORM**

Loc ID 335399 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rider, Lindsay	970-285-2711	cogcc.inspections@caerusoila ndgas.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299111	WELL	PR	09/30/2009	GW	045-17563	GMR 33-2D1(G33NW)	PR
299149	WELL	PR	09/30/2009	GW	045-17575	GMR 34-12B(G33NW)	PR
299150	WELL	PR	01/19/2010	GW	045-17576	GMR 33-2D(G33NW)	PR
299151	WELL	PR	09/30/2009	GW	045-17577	GMR 33-8(G33NW)	PR
299158	WELL	PR	09/30/2009	GW	045-17578	GMR 33-10A(G33NW)	PR
299159	WELL	PR	09/26/2009	GW	045-17579	GMU 33-3D1(G33NW)	PR

General Comment:[Routine Field Inspection.](#)[Any corrective actions from previous inspections that have not been addressed are still applicable.](#)

Location				
Lease Road:				
Type	Access			
comment:	Snow packed.			
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:	1-800-791-7691		Date:	
Corrective Action:			Date:	
Good Housekeeping:				
Type	TRASH			
Comment:				
Corrective Action:			Date:	
Type	DEBRIS			
Comment:				
Corrective Action:			Date:	
Type	OTHER			
Comment:	Stained ground in battery containment and next to the North side of the verticle separators, see photos.			
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e..		Date:	03/04/2019
Type	OTHER			
Comment:	Unmarked flow line riser behind separators.			
Corrective Action:	Comply with 603.f. For unused , unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser		Date:	03/04/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	sheep fence.			
Corrective Action:			Date:	
Equipment:				
Type: Pig Station	# 1			corrective date
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 6			
Comment:				

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:	Mechanical condition of tank valves, see photo.				
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 03/04/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	299111	Type:	WELL	API Number:	045-17563	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299149	Type:	WELL	API Number:	045-17575	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299150	Type:	WELL	API Number:	045-17576	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299151	Type:	WELL	API Number:	045-17577	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299158	Type:	WELL	API Number:	045-17578	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	299159	Type:	WELL	API Number:	045-17579	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401924233	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720316
689303129	Inspection photo 689303129	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4720311