

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/07/2019

Submitted Date:

02/07/2019

Document Number:

689303182

FIELD INSPECTION FORM

Loc ID 383325 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301714	WELL	PR	06/15/2010	GW	045-18233	GGU MILLER 33B-31-691	PR
301715	WELL	PR	06/28/2010	GW	045-18234	GGU MILLER 33A-31-691	PR
301716	WELL	PR	06/28/2010	GW	045-18235	GGU MILLER 34B-31-691	PR
301717	WELL	PR	06/28/2010	GW	045-18236	GGU MILLER 34C-31-691	PR
301718	WELL	PR	06/28/2010	GW	045-18237	GGU MILLER 34A-31-691	PR
301719	WELL	PR	06/28/2010	GW	045-18238	GGU MILLER 34D-31-691	PR
301721	WELL	PR	06/15/2010	GW	045-18239	GGU MILLER 33C-31-691	PR

General Comment:

[Routine Field Inspection.](#)

Location			
Lease Road:			
Type	Access		
comment:	Snow covered, plowed open.		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:
Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel gates		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors	# 14		corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:

Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	chemical units at wellheads.		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	STEEL AST		,
Comment:	625 bbl tanks, 3 tanks are heated.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	OTHER	STEEL AST		,
Comment:	4 tanks are heated, 625 bbl				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	YES		
Comment:	Bradenhead open to vent per sundry notice.		
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	301714	Type:	WELL	API Number:	045-18233	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301715	Type:	WELL	API Number:	045-18234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301716	Type:	WELL	API Number:	045-18235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301717	Type:	WELL	API Number:	045-18236	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301718	Type:	WELL	API Number:	045-18237	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301719	Type:	WELL	API Number:	045-18238	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	301721	Type:	WELL	API Number:	045-18239	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303183	Inspection photo 689303183	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728314