

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/07/2019

Submitted Date:

02/07/2019

Document Number:

689303188**FIELD INSPECTION FORM**
 Loc ID 335028 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**26 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S
Aaron, Axelsson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300560	WELL	PR	01/27/2010	GW	045-17944	MILLER 24D-5-791	PR
300561	WELL	PR	01/27/2010	GW	045-17945	MILLER 24C-5-791	PR
300562	WELL	PR	01/27/2010	GW	045-17946	MILLER 24B-5-791	PR
300563	WELL	PR	01/27/2010	GW	045-17947	MILLER 24A-5-791	PR
300564	WELL	PR	03/01/2010	GW	045-17948	MILLER 13D-5-791	PR
300565	WELL	PR	03/01/2010	GW	045-17949	MILLER 13A-5-791	PR
300581	WELL	PR	12/14/2009	GW	045-17950	MILLER 14D-5-791	PR
300582	WELL	PR	12/11/2009	GW	045-17951	MILLER 14C-5-791	PR
300583	WELL	PR	12/14/2009	GW	045-17952	MILLER 14B-5-791	PR
300584	WELL	PR	12/11/2009	GW	045-17953	MILLER 14A-5-791	PR
300585	WELL	PR	03/01/2010	GW	045-17954	MILLER 13B-5-791	PR
300587	WELL	PR	03/01/2010	GW	045-17955	MILLER 13C-5-791	PR

**General Comment:**Routine Field Inspection.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Snow covered, plowed open.		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-921-8252

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Flow Line	# 1		
Comment:	Water transfer lines.		
Corrective Action:		Date:	
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Chemical units at wellheads.		
Corrective Action:			Date:
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	500 BBLs	HEATED STEEL AST		,	
Comment:	2 tanks are not heated.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES	
Comment:	Bradenhead valves open top vent per sundry notice.	
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	300560	Type:	WELL	API Number:	045-17944	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300561	Type:	WELL	API Number:	045-17945	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300562	Type:	WELL	API Number:	045-17946	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300563	Type:	WELL	API Number:	045-17947	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300564	Type:	WELL	API Number:	045-17948	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300565	Type:	WELL	API Number:	045-17949	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300581	Type:	WELL	API Number:	045-17950	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Well Producing on plunger lift.								
Corrective Action:						Date:			
Facility ID:	300582	Type:	WELL	API Number:	045-17951	Status:	PR	Insp. Status:	PR

<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 300583    Type: WELL    API Number: 045-17952    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 300584    Type: WELL    API Number: 045-17953    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 300585    Type: WELL    API Number: 045-17954    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	
Facility ID: 300587    Type: WELL    API Number: 045-17955    Status: PR    Insp. Status: PR			
<b><u>Producing Well</u></b>			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303189	Inspection photo 689303189	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728317">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728317</a>