

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 1 WH

Photo 2 TNK BTRY

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 3 Unmarked riser not plugged or LOTO

Photo 4 Unused equipment cement PU pad

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 5 Unmarked riser not plugged or LOTO




Photo 6 Stained soil. Unmarked riser not plugged or LOTO

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 7 Unmarked riser's not plugged or LOTO



Photo 8 Stained soil in back of crude oil tank

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 9 Load line to crude oil tank not bull plugged

Photo 10 unused equipment

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 11 TRASH bucket with trash under sep



Photo 12 Leaking VLV on sight glass and stained soil inside SEP

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729




Photo 13 Sep and meter run pic

Photo 14 meter not calibrated since 2005

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 15 Unused equipment unused meter run

Photo 16 berms inadequate

Inspection Photos
Location Name: John A Kunzman #1
Location ID: 317729



Photo 17 Berms inadequate