

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 1 WH



Photo 2 PU

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 3 stained soil around PU motor



Photo 4 Stained soil around PU exhaust

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 5 Stained soil around PU base



Photo 6 Stained soil Around WH

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 7 PU



Photo 8 PU/WH

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 9 loc pic



Photo 10 Emergency number not a working number

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 11 TNK BTRY



Photo 12 Emergency number goes to voicemail of George Gugger

Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 13 TNK BTRY



Photo 14 TNK BTRY



Inspection Photos
Location Name: Sawyer #32-2
Location ID: 327177



Photo 15 Meter run LOTO



Photo 16 leaking fitting and stained soil inside separator