

Inspection Photo (s)
Specialty 43C-21
API # 05-045-14823
Inspection # 689303235



Location Photo #1



Location Photo #2

Inspection Photo (s)
Specialty 43C-21
API # 05-045-14823
Inspection # 689303235



Location Photo #3



Location Photo #4, Stained ground under access stairs into battery containment.

Inspection Photo (s)
Specialty 43C-21
API # 05-045-14823
Inspection # 689303235



Location Photo #5, Stained ground under tank valves, mechanical condition of pipe fittings.



Location Photo #6, Stained ground under tank valves, mechanical condition of pipe fittings. Condensate on ground.

Inspection Photo (s)
Specialty 43C-21
API # 05-045-14823
Inspection # 689303235



**Location Photo #7, Condensate on ground,
stained material.**



**Location Photo #8, Mechanical condition of
tank.**