

Inspection Photos

API: 05-071-08810

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/8/2019

Inspection Photos



Photo 1. Facing north along the access road. The access road has not been reclaimed.

Inspection Photos



Photo 2. Facing northwest along the access road.

Inspection Photos



Photo 3. Facing north at the location.

Inspection Photos



Photo 4. It appears the location was recontoured and seeded. Vegetation has not yet established.

Inspection Photos



Photo 5. The road appears to continue past the location.

Inspection Photos



Photo 6. North side of the location facing south.