

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2019

Submitted Date:

02/13/2019

Document Number:

689303238**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 324130 _____ Holtz, Darin _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258526	WELL	PR	09/01/2004	GW	045-07642	PORTER FEDERAL 11-28	PR

General Comment:

Routine Field Inspection.

Location

Lease Road:			
Type	Access		
comment:	Snow packed, icy.		
Corrective Action		Date:	

Overall Good: ☒

Emergency Contact Number:	
Comment:	1-800-921-8252
Corrective Action:	
Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Hog panel fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	200 BBLs	HEATED STEEL AST		,	
Comment:	1 tank is not heated.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:	Bradenhead valves open top vent per sundry notice.	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	258526	Type:	WELL	API Number:	045-07642	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well producing on plunger lift.								
	Mechanical conditions of master valve, see photo.								
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.						Date:	03/15/2019	

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303239	Inspection photo 689303239	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4733963