

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2019

Submitted Date:

02/07/2019

Document Number:

687903745**FIELD INSPECTION FORM**
 Loc ID 334304 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------------|
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Inspections, All | | SanJuanCOGCC@bp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 273464 | WELL | PR | 08/12/2004 | GW | 067-08971 | JONES 34-16 2 | PR |
| 299501 | WELL | PR | 05/18/2010 | GW | 067-09644 | JONES 34-16 4 | PR |

General Comment:[Downloadable photos at end of inspection report.](#) [Location covered in snow at time of inspection.](#)

| Location | | | | |
|--|---|--------|--|------------------|
| Lease Road: | | | | |
| Type | Access | | | |
| comment: | Gravel road. | | | |
| Corrective Action | L | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Framed metal sign at entrance to location. | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | Emergency contact information is up to date. (970) 247-6916/911 | | | |
| Corrective Action: | | | | Date: _____ |
| Good Housekeeping: | | | | |
| Type | UNUSED EQUIPMENT | | | |
| Comment: | Unused piping, blinds, valves laying on ground by separator and wellhead. | | | |
| Corrective Action: | Please comply with Rule 603.f. | | | Date: 03/07/2019 |
| Overall Good: <input type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | SEPARATOR | | | |
| Comment: | Cattle panel around separator, tank and meter house. | | | |
| Corrective Action: | | | | Date: |
| Type | LOCATION | | | |
| Comment: | Location fenced with Barb wire. | | | |
| Corrective Action: | | | | Date: |
| Type | WELLHEAD | | | |
| Comment: | Cattle panel | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bird Protectors | # 1 | | | corrective date |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Prime Mover | # 2 | | | |
| Comment: | | | | |

| | | | |
|-----------------------------------|----------|-------|--|
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Wellhead | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|-----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <100 BBLS | PBV STEEL | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 273464 | Type: WELL | API Number: 067-08971 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

| | | | | |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 299501 | Type: WELL | API Number: 067-09644 | Status: PR | Insp. Status: PR |
|---------------------|------------|-----------------------|------------|------------------|

Producing WellComment: [Producing.](#)

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 401932865 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728163 |
| 687903746 | Location Sign | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728156 |
| 687903747 | Unused equipment. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728157 |
| 687903750 | Unused equipment at wellhead. | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4728158 |