

Inspection Photos
Location Name: William D Lansdown #1
Location ID: 317613



Photo 1 WH/PU Sign faded and in disrepair

Photo 2 electric panel knocked over

Inspection Photos
Location Name: William D Lansdown #1
Location ID: 317613



Photo 3 Hoz Sep

Photo 4 Unused unmarked and not LOTO riser

Inspection Photos
Location Name: William D Lansdown #1
Location ID: 317613



Photo 5 Meter run Unused, unmarked and not LOTO risers

Photo 6 Produced water tank. Berms not adequate and in disrepair.

Inspection Photos
Location Name: William D Lansdown #1
Location ID: 317613



Photo 7 Unused, unmarked and not LOTO risers and stained soil



Photo 8 TNK BTRY Loc sign faded, NFPA placards torn off

Inspection Photos
Location Name: William D Lansdown #1
Location ID: 317613



**Photo 9 location does not have proper drainage reeling
across location**

Photo 10 Vert Sep building in disrepair