

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



Colorado Oil and Gas Conservation Commission  
40.10371, -104.81744, 1469.3m  
Feb 14, 2019 12:32:18 PM



Colorado Oil and Gas Conservation Commission  
40.10367, -104.81746, 1468.3m  
Feb 14, 2019 12:32:35 PM

**Photo 1 PU**

**Photo 2 WH**

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Photo 3 TNK BTRY**



**Photo 4 no bull plug on crude oil load line**



**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Photo 5 no bull plug crude oil tank load line**



**Photo 6 Stained soil horizontal separator**



**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Photo 7 stained soil appeared to have leak in front of sep**




**Photo 8 Stained soil in front of separator**



**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



**Photo 9 stained soil appeared to have leak in front of sep**



**Photo 10 Stained soil inside sep house**

**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



Colorado Oil and Gas Conservation Commission  
40.10342, -104.81635, 1475.5m  
Feb 14, 2019 12:37:04 PM

**Photo 11 fluid on 2" piping inside sep house**



Colorado Oil and Gas Conservation Commission  
40.10343, -104.81627, 1469.2m  
Feb 14, 2019 12:37:37 PM

**Photo 12 unused unmarked and not LOTO riser**



**Inspection Photos**  
**Location Name: Millard #1**  
**Location ID: 333131**



Colorado Oil and Gas Conservation Commission  
40.10335, -104.81624, 1471.5m  
Feb 14, 2019 12:37:58 PM

**Photo 13 Unused equipment**



Colorado Oil and Gas Conservation Commission  
40.10327, -104.81635, 1471.3m  
Feb 14, 2019 12:38:40 PM

**Photo 14 Loc pic**