

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2019

Submitted Date:

02/14/2019

Document Number:

688800467

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
325354 \_\_\_\_\_ Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 74500

Name of Operator: REYNOLDS\* NOEL

Address: BOX 356

City: FLORA VISTA State: NM Zip: 87415

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                     | Comment |
|---------------|-------|---------------------------|---------|
| Spencer, Stan |       | stan.spencer@state.co.us  |         |
| Andrews, Dave |       | david.andrews@state.co.us |         |
| Fischer, Alex |       | alex.fischer@state.co.us  |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 119826      | PIT  |        |             |            | -         | ESTER 1       | EI          |
| 214628      | WELL | SI     | 03/01/1993  | GW         | 067-06232 | ESTER 1       | EI          |

**General Comment:**

On February 13, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Noel Reynolds Ester #1. Cottonwood Consulting representatives were on site during this field inspection. The purpose of this inspection was to document existing conditions and evaluate the viability of proposed subsurface investigation techniques. For the most recent field inspection report of this facility, please refer to document #685303902. Site conditions at this orphaned location appeared to be similar as to how they were observed during that inspection.

**Location**

|                    |   |       |  |
|--------------------|---|-------|--|
| <b>Lease Road:</b> |   |       |  |
| Type               | Access  |       |  |
| comment:           | Access road appears to enter location in NE corner. A power line road from the south does not appear to have an access point to the location. |       |  |
| Corrective ActionL |   | Date: |  |

Overall Good:

Emergency Contact Number:

|                    |  |       |       |
|--------------------|--|-------|-------|
| Comment:           |  |       |       |
| Corrective Action: |  | Date: | _____ |

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | UNUSED EQUIPMENT  |       |  |
| Comment:           | Electric supply panel.  |       |  |
| Corrective Action: |   | Date: |  |
| Type               | DEBRIS  |       |  |
| Comment:           | Area around well head is littered with trash and debris. Pallets, old wooden beams, hoses, and pieces of PVC pipe remain on location. |       |  |
| Corrective Action: |   | Date: |  |

Overall Good:

**Spills:**

| Type   | Area | Volume |  |  |
|--|------|--------|--|--|
| In Containment: No                                     |      |        |  |  |
| Comment:   |      |        |  |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |  |

**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | PIT   |       |  |
| Comment:           | T post and wire fencing around pit is in disrepair. |       |  |
| Corrective Action: |   | Date: |  |

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 119826 Type: PIT API Number: - Status:        Insp. Status: EI

Facility ID: 214628 Type: WELL API Number: 067-06232 Status: SI Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_  
Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long -108.148333  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_  
Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

\_\_\_\_\_

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: NO Pit ID: 119826 Lat: 37.084217 Long: -108.148906

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: 20 Width: 12

**Lining:**

Liner Type: Plastic Liner Condition: \_\_\_\_\_

Comment: Unlined earthen pit with stained soil on western side.

Corrective Action:

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Inadequate

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: YES 2+ feet Freeboard: \_\_\_\_\_

Comment: Puddle of oil noted in previous inspections.

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p>On February 13, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Noel Reynolds Ester #1. Cottonwood Consulting representatives were on site during this field inspection. The purpose of this inspection was to document existing conditions and evaluate the viability of proposed subsurface investigation techniques. For the most recent field inspection report of this facility, please refer to document #685303902. Site conditions at this orphaned location appeared to be similar as to how they were observed during that inspection.</p> <p>Patchy snow covered parts of the location during this inspection. Stained soil was observed in the western end of Pit ID #119826. A 2" stand pipe, with approximately 8" of stick up was noted adjacent to the pit.</p> <p>A mound of grey black soil was observed along the southern edge of the location. The native soil in the area is red brown clay and silt. Gravel and cobbles were observed in undisturbed areas near the location.</p> | hughesjo | 02/14/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 688800468    | Inspection Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735585">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735585</a> |