

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/01/2019

Submitted Date:

02/08/2019

Document Number:

688000260

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 7800  
Name of Operator: BEREN CORPORATION  
Address: 2020 N BRAMBLEWOOD STREET  
City: WICHITA State: KS Zip: 67206

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Reynolds, Rodney	(316) 337-8340	reynoldsr@berexco.com	<a href="#">AI inspections</a>

**General Comment:**

Environmental inspection related to Rem #10290, closure of former production pit ID 111968. Pit has been backfilled using berm material and additional fill sourced from an area southwest of the pit location adjacent to and northeast of the county road and canal.

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID: 111968      Lat: 40.654951      Long: -103.278531

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment: Pit has been backfilled and regraded. Location is open and accessible enough to allow for trenching in the vicinity of MW-06 to allow additional investigation of the extent of LNAPL.

Corrective Action: Contact NE EPS to discuss a schedule for on site observation of additional LNAPL investigation.

Date: 02/28/2019

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401934294	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729710</a>
688000261	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729700">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4729700</a>