

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2019

Submitted Date:

02/11/2019

Document Number:

695100164**FIELD INSPECTION FORM**
 Loc ID 308507 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273107	WELL	PR	12/16/2004	GW	071-08140	LORENCITO 2-7-34-66	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	LOCATION SIGN		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	UNUSED EQUIPMENT STORED ON LOCATION		
Corrective Action:	Comply with Rule 603.f .	Date:	03/11/2019
Type	OTHER		
Comment:	STAINED SOIL NEAR PRIME MOVER ON PUMP JACK SKID.		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.	Date:	03/11/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	TELEMETRY EQUIPMENT		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	LAST CALIBRATION 10/30/18		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	BRADEN HEAD PLUMBED TO SURFACE		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:	
Type	

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 273107	Type: WELL	API Number: 071-08140	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: YESPit ID: 278690Lat: 37.104624Long: -104.819297Reference Point: SE

Other: _____

Length: 70Width: 30**Lining:**

Liner Type:

Liner Condition: Adequate

Comment:

Corrective Action

Date:

Fencing:Fencing Type: WildlifeFencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment: NONE

Corrective Action

Date:

Anchor Trench Present: YESOil Accumulation: NO2+ feet Freeboard: NO

Comment:

PRODUCED WATER APPEARS TO BE ABOVE THE 2' FREEBOARD. FREEBOARD MARKER IS NOT INSTALLED ON THE LOWEST ELEVATION OF PIT.

Corrective Action

MOVE FREEBOARD MARKER TO THE LOWEST BANK OF PIT. Lower fluid level so at least two feet of freeboard exists per Rule 902.b.Date: 02/12/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401936091	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4731401
695100165	LOCATION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4731392