

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/13/2019

Submitted Date:

02/14/2019

Document Number:

682600625**FIELD INSPECTION FORM**Loc ID 321669 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 51065Name of Operator: LOEB LLC* HERMAN LAddress: P O BOX 838City: LAWRENCEVILLE State: IL Zip: 62439**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Middagh, Jesse	815-556-0756	jesse@loeboil.com	
Pelton, Shane	620-617-5870	shane@loeboil.com	
,	,	dnr_cogccengineering@state.co.us	COGCC Engineering
,	,	dnr_cogccenforcement@state.co.us	COGCC Enforcement
Pesicka, Conor		conor.pesicka@state.co.us	
Axelson, John		john.axelson@state.co.us	
Sutphin, Dirk		dirk.sutphin@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207726	WELL	PR	06/26/1998	OW	017-06661	WHITE 'AM' 1	EI

General Comment:

This is a follow up inspection to COGCC Inspection # 682600612 which found gas venting from a valve on the wellhead. At the time of this inspection on 2/13/2019 the valve that was previously venting has been removed leaving an open pipe actively venting methane gas (see attached photos).

Previous corrective action to update operator contact information has been fixed.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	YES		
Comment:	Gas being vented or flared during non-upset condition without prior approval from COGCC. I observed a steady, forceful stream of gas being vented via an open pipe off the wellhead and a 4 gas meter detected methane gas. See attached photos.		
Corrective Action:	Since the flaring or venting occurred after flowback without approval, contact the COGCC Area Engineer for next steps per Rule 912.b. if operator intends to continue venting. If operator intends to cease venting operator should install plug or valve to cease venting and document fix on an FIRR form.	Date:	02/02/2019

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 207726 Type: WELL API Number: 017-06661 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401939783	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4734689
682600634	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4734688