

Inspection Photos

API: 05-071-08360

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/14/2019

Inspection Photos



Photo 1. Facing west at the beginning of the access road.

Inspection Photos



Photo 2. Facing west along the access road.

Inspection Photos



Photo 3. Facing south toward the location. The access road continues past the location.

Inspection Photos



Photo 4. Facing southeast toward the location.

Inspection Photos



Photo 5. Facing north toward the location.

Inspection Photos



Photo 6. East side of the location facing southwest. It appears cattle having been grazing the site.

Inspection Photos



Photo 7. The vegetation at the location has not established. Additional reseeding needs to be performed.

Inspection Photos



Photo 8. There is very little vegetation along the cut slope.