

Inspection Photos

API: 05-071-07045

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 2/14/2019

Inspection Photos



Photo 1. Facing southeast toward the location.

Inspection Photos



Photo 2. Facing south toward the pit. This area has recently been hydromulched.

Inspection Photos



Photo 3. Facing toward the wellhead. Well sign is present.

Inspection Photos



Photo 4. A new lined pit appears to have been installed.

Inspection Photos



Photo 5. Tanks are properly labeled.