

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2019

Submitted Date:

02/14/2019

Document Number:

675001940**FIELD INSPECTION FORM**Loc ID 312548 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments6 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@qwestoffice.net	
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221891	WELL	PR	10/01/2018	GW	077-08493	USA 1-18 JC	SI

General Comment:

This is a Follow up field inspection to inspection 689401441 dated 7/3/18, any corrective actions not addressed from previous inspections are still applicable.
This well is not listed in the AOC 1V-609

Location			
Lease Road:			
Type	Access		
comment:	Access road not maintained		
Corrective Action	Repair and maintain lease road.		Date: 03/15/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Battery sign faded (Tank sign is not legible.), (No wellhead sign,)		
Corrective Action:	Install sign to comply with rule 210		Date: 11/03/2018
Emergency Contact Number:			
Comment:	Posted Emergency Contact Number 1-970-585-8550 911 Not posted		
Corrective Action:	Install sign to comply with rule 210		Date: 03/15/2019
Good Housekeeping:			
Type	DEBRIS		
Comment:	Vegetation and vegetation debris in tank containment and around equipment.		
Corrective Action:	Remove to comply with Rule 603.f		Date: 11/03/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		STEEL AST		,	
Comment:	See sign section of inspection.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate	
Comment:	See housekeeping section of inspection. Berm is eroding				
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date:	03/15/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	221891	Type:	WELL	API Number:	077-08493	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Shut in at wellhead. L Last production shown is July 2018</div>									
Corrective Action: _____ Date: _____									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
		Compaction				
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:

Liner Type:

Liner Condition:

Comment:

No Facility ID for second pit on location.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 11/03/2018**Fencing:**Fencing Type: WildlifeFencing Condition: AdequateComment:

Corrective Action

Date: **Netting:**

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401941386	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735991
675001941	Inspection 675001940 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735983