

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2019

Submitted Date:

02/15/2019

Document Number:

675001944**FIELD INSPECTION FORM**Loc ID 312561 Inspector Name: Wentzel, Dougo On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		aak2@kahnjeeholding.com	All Inspections
, DNR		dnr_cogccengineering@state.co.us	All Engineering
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Graves, Jim		mrinc20@qwestoffice.net	
Ried, Jordan	970-563-400	maralextechjr@gmail.com	All Inspections
Peicka, Conor		conor.pesicka@state.co.us	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221908	WELL	SI	07/09/1984	GW	077-08510	USA 1-9C	TA

General Comment:

This is a follow up inspection to FIR Doc#675203581. Any corrective actions not addressed from previous inspections are still applicable.
 This well is listed on AOC 1V-609
 Cannot access road not maintained

Location

Lease Road:			
Type	Access		
comment:	Cannot access road not maintained Comments from previous inspection on road Main road has multiple areas of erosion across roadway and sediment migration down gradient of road surface. This location is a federal surface hence the inspection is being forwarded to a BLM representative so they may respond to the operator on what actions should be implemented. The road would not meet the COGCC stormwater rules for erosion and sediment migration.		
Corrective Action:	Repair and maintain lease road.	Date:	03/18/2019

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 221908 Type: WELL API Number: 077-08510 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: No current MIT on file. A mechanical integrity test shall be performed on each temporarily abandoned well within 30 days of temporarily abandoning the well. No current Form 4 on file for continued TA status. A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. According to AOC 1V-609 order #11 annual submission is still required.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 09/24/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401941388	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735993
675001945	Inspection 675001944 photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4735985