

Construction and Stormwater Inspection

February 20-22, 2019

Operator: ELEVATION MIDSTREAM LLC – 10687

Location ID: 460416

Inspection Document #: 674902607

Weld County, CO

NE Section 30 T1N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 1. Photo taken from the northern perimeter of the location looking at the access road off CR 6, facing West. Operator is in the process of installing gravel to potentially to limit tracking onto the county road.



Photo 2. Photo taken from the northern perimeter of the location, facing East. Appears the operator has placed gravel over a geo textile fabric on top of the existing top soil.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 3. Photo taken from the northern perimeter of the location, facing South. See comments from Photo 2.



Photo 4. Photo taken from the northern perimeter of the location, facing South. Photo depicts potentially top soil not salvaged and that BMP's have not been installed around the entire perimeter of the location.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 5. Photo taken from the northern perimeter of the location, facing South. See comments from Photo 4.



Photo 6. Photo taken from the Southern perimeter of the location, facing West. Photo depicts a temporary pond installed to fill water trucks.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 7. Photo taken from the southern perimeter of the location, facing West. Photo depicts BMP's installed around the parts of the southern perimeter of the location.



Photo 8. Photo taken from the Southern perimeter of the location, facing West. See comments from Photo 7.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 9. Photo taken from the western perimeter of the location, facing Southwest. Photo depicts BMP's have not been installed around the entire perimeter of the location and note the wetland on the left in the Photo.



Photo 10. Photo taken from the Southern perimeter of the location, facing North. Photo illustrates a topsoil stockpile being stored along the southern area and is being temporarily stabilized with equipment tracking.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 11. Photo taken from the southern perimeter of the location, facing North. Photo illustrates the second topsoil stockpile being stored along the southern area. Note the soil color change in the left of the photo. Appears the Operator was placing subsoil on top of the topsoil stockpile.



Photo 12. Photo taken from the western perimeter of the location, facing Northeast. See comments from Photo 11.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 13. Photo taken from the western perimeter of the location, facing East. See comments from Photo 11.



Photo 14. Photo taken from the western perimeter of the location, facing North. Photo depicts BMP's have not been installed around the entire perimeter of the location and note the wetland on the left in the Photo.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 15. Photo taken from the eastern perimeter of the location, facing Southwest. Photo depicts 1 of 2 topsoil test pits excavated on location in the undisturbed area. Topsoil averaged approximately 9 inches observed across all test pits.



Photo 16. Photo taken from the eastern perimeter of the location. See comments from Photo 15.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 17. Photo taken from the eastern perimeter of the location, facing East. Photo depicts 2 of 2 topsoil test pits excavated on location in the undisturbed area. Topsoil averaged approximately 9 inches observed across all test pits.



Photo 18. Photo taken from the eastern perimeter of the location. See comments from Photo 17.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 19. Photo taken from the eastern perimeter of the location, facing Southwest. Photo depicts 1 of 3 topsoil test pits taken on location in the disturbed area that topsoil salvage operations were said to be complete by the Operator.



Photo 20. Photo taken from the eastern perimeter of the location. Photo depicts approximately 3 inches of top soil remaining in pit 1 of 3 within the disturbed area that topsoil salvage operations were said to be complete by the Operator.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 21. Photo taken from the southern perimeter of the location, facing Southwest. Photo depicts 3 of 3 topsoil test pits taken on location in the disturbed area that topsoil salvage operations were said to be complete by the Operator.



Photo 22. Photo taken from the eastern perimeter of the location. Photo depicts approximately 8 inches of top soil remaining in pit 3 of 3 within the disturbed area that topsoil salvage operations were said to be complete by the Operator.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 23. Photo taken from the southern perimeter of the location, facing West. Photo depicts a cut area where topsoil salvage operations were had been done by the Operator.



Photo 24. Photo taken from the eastern perimeter of the location. Photo depicts a topsoil depth of approximately 11 inches observed.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 25. Photo taken from the southern perimeter of the location, facing North. Photo illustrates the second topsoil stockpile being stored along the southern area. Appears the Operator was still placing subsoil on top of the topsoil stockpile as of 2/22/2019.



Photo 26. Photo taken from the southern perimeter of the location, facing North. Photo illustrates the area adjacent to the second topsoil stockpile being stored along the southern area. Note the soil color changes from the subsoil in the background to the topsoil in the foreground.

Inspection Photos

Location Name: ELEVATION MIDSTREAM LLC/1N67W30

Location ID: 460416



Photo 27. Photo taken from the southern perimeter of the location, facing East. Photo illustrates the first topsoil stockpile being stored along the southern area. Appears the Operator has not stabilized parts of the stockpile.



Photo 28. Photo taken from the southern perimeter of the location, facing West. Photo illustrates the first topsoil stockpile being stored along the southern area. Appears the Operator has not stabilized parts of the stockpile.