

**FORM
INSP**Rev
X/15

State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/15/2019

Submitted Date:

02/15/2019

Document Number:

689303267**FIELD INSPECTION FORM**

Loc ID 311621	Inspector Name: Holtz, Darin	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10447</u> Name of Operator: <u>URSA OPERATING COMPANY LLC</u> Address: <u>1600 BROADWAY ST STE 2600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				Findings: 12 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278666	WELL	PR	11/01/2018	GW	045-10909	NORTH BANK B1	PR
284841	WELL	PR	11/01/2018	GW	045-12293	NORTH BANK B2	PR
285220	WELL	PR	11/01/2018	GW	045-12418	NORTH BANK B4	PR
285221	WELL	PR	08/01/2012	GW	045-12417	NORTH BANK B7 PA	PR
285225	WELL	PR	03/01/2015	GW	045-12415	NORTH BANK B5	PR

General Comment:[Routine Field Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 1-855-625-9922

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Stained ground at blowdown on the separator, see photos.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.. Contact area COGCC EPS	Date:	02/26/2019

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	

Equipment:

corrective date

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at wellhead.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	3	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST		,	
Comment: 6 tanks in centralized battery.						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID:	278666	Type:	WELL	API Number: 045-10909 Status: PR Insp. Status: PR
Producing Well				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	284841	Type:	WELL	API Number: 045-12293 Status: PR Insp. Status: PR
Producing Well				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	285220	Type:	WELL	API Number: 045-12418 Status: PR Insp. Status: PR
Producing Well				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	285221	Type:	WELL	API Number: 045-12417 Status: PR Insp. Status: PR
Producing Well				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		
Facility ID:	285225	Type:	WELL	API Number: 045-12415 Status: PR Insp. Status: PR
Producing Well				
Comment:	Well Producing on plunger lift.			
Corrective Action:		Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401943459	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737957
689303268	Inspection photo 689303268	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737951