

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401929778  
Date Received:  
02/06/2019

## FIR RESOLUTION FORM

### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 39560  
Name of Operator: TOP OPERATING COMPANY  
Address: 3609 S WADSWORTH BLVD STE 340  
City: LAKEWOOD State: CO Zip: 80235  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Herring, Paul	303-727-9915	paul.herring@topoperating.com
Gomez, Jason		jason.gomez@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 688401131  
Inspection Date: 01/23/2019 FIR Submit Date: 01/23/2019 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TOP OPERATING COMPANY Company Number: 39560  
Address: 3609 S WADSWORTH BLVD STE 340  
City: LAKEWOOD State: CO Zip: 80235

### LOCATION - Location ID: 321259

Location Name: TANAKA BROS-61N69W Number: 2NESE County: BOULDER  
Qtrqr: NESE Sec: 2 Twp: 1N Range: 69W Meridian: 6  
Latitude: 40.078830 Longitude: -105.078500

### FACILITY - API Number: 05-013- -00 Facility ID: 206541

Facility Name: TANAKA BROS Number: 1  
Qtrqr: NESE Sec: 2 Twp: 1N Range: 69W Meridian: 6  
Latitude: 40.078830 Longitude: -105.078500

### CORRECTIVE ACTIONS:

1 ☒ CA# 121988

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 02/23/2019

Response: CA COMPLETED

Date of Completion: 01/21/2019

Operator Comment: A neighbor (Phil Irwin) called TOP about the seperator on Sunday, January 20. TOP personal went to the facility that day and noticed that, although the seperator was operating properly, a moderate "humming" sound was periodically coming from the seperator when the burner for the seperator was activated. TOP personal turned off the gas supply to the seperator and called in a third party to diaganose the seperator Monday, January 21. The

separator was in working order but the burner feed was causing a minor vibration against the wall of the separator. Although the sound and vibrations was within COGCC decibel limits and NOT affecting the operation of the separator, TOP adjusted the burner so that the vibration did not occur.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 121989

Corrective Action: Location is within a designated setback location, mark guy line anchors per Rule 604.c. (2)Q.

Date: 02/13/2019

Response: CA COMPLETED

Date of Completion: 01/31/2019

Operator  
Comment: Anchors have identified, see attached photos

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Paul Herring

Signed: \_\_\_\_\_

Title: Landman

Date: 2/6/2019 1:40:49 PM

#### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401929778	FIR RESOLUTION SUBMITTED
401930705	Anchor 1
401930709	Anchor 2
401930712	Anchor 3

Total Attach: 4 Files