

Inspection Photos

2/27/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 432189

Inspection Doc. Number: 682504529

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the north end of the location, facing east. Photo 1-4 provide an overview of the location (interim and production areas) from east, southeast, southwest to west.



Photo 2: See comments under photo 1.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 432189



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.



Photo 5: Photo taken from the northwest end of the location, facing west. Photo shows interim areas of the location are predominantly bare and exposed soil, or undesirable weedy plant species such as Kochia and Salsola sp. Areas are not progressing towards reclamation requirements.



Photo 6: Photo taken from the northwest end of the location. Photo shows interim areas of the location are predominantly bare and exposed soil, or undesirable weedy plant species such as Kochia and Salsola sp. Areas are not progressing towards reclamation requirements.



Photo 7: Photo taken from the northwest end of the location, facing southeast. Photo shows interim areas of the location are predominantly bare and exposed soil, or undesirable weedy plant species such as Kochia and Salsola sp. Areas are not progressing towards reclamation requirements.



Photo 8: Photo taken from the northwest end of the location, facing south. Photo shows interim areas of the location are predominantly bare and exposed soil, or undesirable weedy plant species such as Kochia and Salsola sp. Areas are not progressing towards reclamation requirements.



Photo 9: Photo taken from the west end of the location. Photo shows gravel/road base remains on portions of the interim areas. Gravel appears to be hindering reclamation.



Photo 10: Photo taken from the west end of the location, facing south. Photo shows interim areas of the location are predominantly bare and exposed soil, or undesirable weedy plant species such as Kochia and Salsola sp. Areas are not progressing towards reclamation requirements.



Photo 11: Photo taken from the west end of the location. Photo shows areas where operator appears to have traveled from the location onto slopes of the interim areas.



Photo 12: Photo taken from the slopes of the interim areas on the southwest end of the location. Photo shows slopes remains predominantly bare and exposed soil with little desirable perennial vegetative establishment. Photo also shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 13: Photo taken from the slopes of the interim areas on the south end of the location, facing southwest. Photo shows slopes remains predominantly bare and exposed soil with little desirable perennial vegetative establishment. Photo also shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 14: Photo taken from the slopes of the interim areas on the southwest end of the location. Photo shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 15: Photo taken from the interim areas on the northeast end of the location. Photo shows areas of the interim that are predominantly undesirable weedy plant species such as Kochia and Salsola sp.