

Inspection Photos

2/27/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 433177

Inspection Doc. Number: 682504533

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the southwest end of the location, facing north. Photos 1-3 provide an overview of the location from north, northeast to east.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 433177



Photo 2: See comments under photo 1.



Photo 3: See comments under photo 1.

Inspection Photos
Operator: NOBLE ENERGY INC - 100322
Location ID: 433177



Photo 4: Photo taken from the south end of the location, facing east. Photo shows operator appears to have installed surface roughening along the southern perimeter.



Photo 5: Photo taken from the southeast end of the location, facing southwest. Photo shows erosion log.



Photo 6: Photo taken from the southeast end of the location, facing southwest. Photo shows erosion log.



Photo 7: Photo taken from the south end of the location, facing south. Photo shows stormwater runoff from the pad appears to have caused degradation on the adjacent areas beyond the location.



Photo 8: Photo taken from the south of the location, facing north. Photo shows stormwater runoff from the pad appears to have caused degradation on the adjacent areas beyond the location.



Photo 9: Photo taken from the south of the location, facing north. Photo shows stormwater runoff from the pad appears to have caused degradation on the adjacent areas beyond the location.



Photo 10: Photo taken from the adjacent reference area. Photo shows vegetation over the reference area.



Photo 11: Photo taken from the slopes of the interim areas on the east end of the location, facing north. Photo shows slopes remains predominantly bare and exposed soil with little desirable perennial vegetative establishment. Photo also shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 12: Photo taken from the slopes of the interim areas on the east end of the location. Photo shows slopes remains predominantly bare and exposed soil with little desirable perennial vegetative establishment. Photo also shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 13: Photo taken from the slopes of the interim areas on the east end of the location, facing southwest. Photo shows slopes remains predominantly bare and exposed soil with little desirable perennial vegetative establishment. Photo also shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 14: Photo taken from the slopes of the interim areas on the east end of the location. Photo shows the erosion blankets/netting along slopes are in disrepair and no longer in proper functioning condition.



Photo 15: Photo taken from the northeast end of the location, facing south. See comments under photo 14.



Photo 16: Photo taken from the northeast end of the location, facing west. See comments under photo 14.