

**Inspection Photos**  
**Location Name: Ute C #3**  
**API: 05-067-07644**



**Lube oil container on secondary containment. Label on container is illegible.**



**Horizontal heated separator has rust colored staining below aluminum elbow.**

Inspection Photos  
Location Name: Ute C #3  
API: 05-067-07644



Rust colored staining present on vessel and gravel beneath aluminum elbow.



Drip pot on AST load out line with ice and fluids present.