

Inspection Photo (s)
Legg 2-26
API #05-045-07049
FIR Inspection # 689303388



Location Photo #1



Location Photo #2

Inspection Photo (s)
Legg 2-26
API #05-045-07049
FIR Inspection # 689303388



Location Photo #3



Location Photo #4, Leaking flange on inlet line to meter run