

Inspection Photo (s)
Werner 31B
API #05-045-19237
FIR Inspection # 689303394



Location Photo #1



Location Photo #2

Inspection Photo (s)
Werner 31B
API #05-045-19237
FIR Inspection # 689303394



Location Photo #3



Location Photo #4, 3 unmarked/unused flow line risers.

Inspection Photo (s)
Werner 31B
API #05-045-19237
FIR Inspection # 689303394



Location Photo #5, 6 unmarked/unused flow line risers.



Location Photo #6 unit 44D has leaking fittings.

Inspection Photo (s)
Werner 31B
API #05-045-19237
FIR Inspection # 689303394



Location Photo #7, leaking fittings below the kimray on unit 44D



Location Photo #8, leaking fittings below the kimray on unit 44D

Inspection Photo (s)
Werner 31B
API #05-045-19237
FIR Inspection # 689303394



Location Photo #9, leaking fitting at the check valve unit 44D



Location Photo #10, Leaking fitting on unit 44B.

Inspection Photo (s)
Werner 31B
API #05-045-19237
FIR Inspection # 689303394



Location Photo #11, leaking fitting at check valve on unit 44B