

Inspection Photo (s)
Epperly 24B
API #05-045-20952
FIR Inspection # 689303396



Location Photo #1



Location Photo #2

Inspection Photo (s)
Epperly 24B
API #05-045-20952
FIR Inspection # 689303396



Location Photo #3



Location Photo #4, Leaking fittings on unit 23D

Inspection Photo (s)
Epperly 24B
API #05-045-20952
FIR Inspection # 689303396



Location Photo #5, 2 leaking fittings on unit 23D



Location Photo #6, leaking fitting on unit 23D

Inspection Photo (s)
Epperly 24B
API #05-045-20952
FIR Inspection # 689303396



Location Photo #7, Stained material under scrubber pot.



Location Photo #8, Stained material under scrubber pot.