

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2019

Submitted Date:

02/28/2019

Document Number:

689303396

FIELD INSPECTION FORM

Loc ID 424796 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

- 27 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Collett, Shane		scollett@vnrenergy.com	Superintendent operations
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
424800	WELL	PR	06/13/2012	GW	045-20942	EPPERLY 23A-23-692	PR
424802	WELL	PR	07/19/2012	GW	045-20943	EPPERLY 13D-23-692	PR
424803	WELL	PR	07/26/2012	GW	045-20944	EPPERLY 14B-23-692	PR
424807	WELL	PR	07/19/2012	GW	045-20945	EPPERLY 13C-23-692	PR
424808	WELL	PR	07/26/2012	GW	045-20946	EPPERLY 24D-23-692	PR
424809	WELL	PR	07/19/2012	GW	045-20947	EPPERLY 13A-23-692	AC
424810	WELL	PR	06/13/2012	GW	045-20948	EPPERLY 23B-23-692	PR
424811	WELL	PR	07/23/2012	GW	045-20949	EPPERLY 23D-23-692	PR
424813	WELL	PR	06/13/2012	GW	045-20950	EPPERLY 23C-23-692	PR
424815	WELL	PR	07/10/2012	GW	045-20951	EPPERLY 13B-23-692	PR
424816	WELL	PR	07/26/2012	GW	045-20952	EPPERLY 24B-23-692	AC
424932	WELL	PR	07/26/2012	GW	045-20979	Epperly 14D-23-692	PR

General Comment:

Routine Field Inspection.
Location is snow covered.

Location			
Lease Road:			
Type	Access		
comment:	Snow packed /icy.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:	1-800-921-8252	Date:	
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	Stained material under scrubber pot. see photos.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e.	Date:	03/04/2019
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	SEPARATOR		
Comment:	Hog panel fence.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Panel gates.		
Corrective Action:		Date:	
Equipment:			
Type: Pig Station	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical units at wellheads.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 12		
Comment:	Leaking fittings on unit 23D, see photos.		

Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	03/04/2019
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	
Type: Plunger Lift	# 12			
Comment:				
Corrective Action:			Date:	
Type: Horizontal Heater Treater	# 1			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLs	HEATED STEEL AST		
Comment:	2 tanks are not heated.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	YES
Comment:	Bradenhead valves open top vent per sundry notice.
Corrective Action:	
	Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	424800	Type:	WELL	API Number:	045-20942	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424802	Type:	WELL	API Number:	045-20943	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424803	Type:	WELL	API Number:	045-20944	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424807	Type:	WELL	API Number:	045-20945	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424808	Type:	WELL	API Number:	045-20946	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424809	Type:	WELL	API Number:	045-20947	Status:	PR	Insp. Status:	AC
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424810	Type:	WELL	API Number:	045-20948	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift.								
Corrective Action:					Date:				
Facility ID:	424811	Type:	WELL	API Number:	045-20949	Status:	PR	Insp. Status:	PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Facility ID: 424813 Type: WELL API Number: 045-20950 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Facility ID: 424815 Type: WELL API Number: 045-20951 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Facility ID: 424816 Type: WELL API Number: 045-20952 Status: PR Insp. Status: AC

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Facility ID: 424932 Type: WELL API Number: 045-20979 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Location is snow covered.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689303397	Inspection photo 689303397	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4749611