

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404



Location Photo #1



Location Photo #2

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404



Location Photo #3

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404



Location Photo #4, Separator 11C-24, has leaking fitting.



Location Photo #5, 11C-24 leaking fitting.

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404



Location Photo #6, Separator 44B has a leaking fitting.



Location Photo #7, 44B leaking fitting.

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404




Location Photo #8, Separator 41C has a leaking fitting.



Location Photo #9, 41C leaking fitting.

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404



Location Photo #10, 41B has 2 leaking fittings.



Location Photo #11, 41B 1 of 2 leaking fitting.

Inspection Photo (s)
Tharp 14D
API #05-045-18607
FIR Inspection # 689303404



Location Photo #12, 41B 2 of 2 leaking fitting.