

## PIT STATUS EVALUATION FORM

Facility ID: 111264

Pit Name: ERICKSON 2-5

☐ Duplicate Record(s) Pit #

## Legend

- Database Pit Location
- Producing Well
- + Shut In Well
- / Temp Aban Well
- / Abandoned Well
- / Dry & Aban Well
- / Injection Well
- Other Well Status



1:6,000  
0 250 500 750 Feet

Image Source:  
USDA National Agricultural Imagery  
Program (NAIP), 2006

S.S. PAPADOPULOS & ASSOCIATES, INC.

## COGCC Database Information

Status: NR Owner: TIMBERLINE ENERGY INC  
T: 6S R: 65W Sec: 2 QQ: SWNW 6th Meridian  
Latitude: 39.560026 Longitude: -104.639821 NAD83

County: Elbert, CO  
County Code: 039

## Pit Status Evaluation

- ☐ Active ☐ Form 15: Pit Permit #581454 (1990) new Assoc. Well Seq No(s) \_\_\_\_\_  
☐ Other documentation \_\_\_\_\_  
☐ Aerial photo verification \_\_\_\_\_
- ☒ Closed ☐ Form 27: Remediation Workplan \_\_\_\_\_  
☒ Form 4: Sundry Notice #581455 (1-9-1991) pit cancellation  
☐ Rule 903a.(2)B \_\_\_\_\_  
☐ Evidence pit(s) existed, no closure docs & well not PR, AC or SI  
 Well API Seq #(s) \_\_\_\_\_  
☐ Other documentation \_\_\_\_\_
- ☐ Abandoned ☐ Possible un-reclaimed pit(s) or adverse conditions, no closure docs ☐ Site Visit  
☐ Unknown ☐ No Site Visit  
☐ Add'l Review

Notes: FIR (2008) Two 300 BBL tanks and fiberglass tank for water storage