

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2019

Submitted Date:

03/04/2019

Document Number:

687903773**FIELD INSPECTION FORM**

Loc ID 311887 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Reed	720-484-2346	Inspections@catamountep.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216304	WELL	PR	07/01/2011	GW	067-07910	F W TERRELL GAS UNIT 2	PR
296161	WELL	PR	06/19/2018	GW	067-09559	IGW 122	PR

General Comment:[This is a follow up inspection refarding document# 687903677. Downloadable photos at end of report.](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Metal framed sign at wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Emergency contact information current. (970) 442-6620		
Corrective Action:		Date:	

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Metal building with unused equipment.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f. Allowing extra time to comply with CA due to weather conditions and time of year.		Date: 05/30/2019
Type	TRASH		
Comment:	oily rags and used parts on pump jack skid have been cleaned up to comply with Rule 603.f.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	300 BBLS	STEEL AST		,
Comment:	Repaired leaking valve and installed bull plug in IGW 122 produced water tank to comply with Rule 605.d.				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Tires/trash have been removed from secondary containment to comply with Rule 603.f.			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 216304	Type: WELL	API Number: 067-07910	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Facility ID: 296161	Type: WELL	API Number: 067-09559	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well

Comment: Producing.

Corrective Action:

Date:

COGCC Comments

Comment

This is a follow up inspection regarding document# 687903677. Some CA's have not been completed due to adverse weather conditions and CA time allotted not being reached, therefore, follow up inspection still required.

User

stewartj

Date

03/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903775	oily rags/parts picked up	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751980
687903776	unused equipment still currently on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751981
687903777	Valve replace and tires/trash removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4751982