

Construction and Stormwater Inspection

February 21, 2019

Operator: NICKEL ROAD OPERATING LLC #10669

Location ID: 454899

Inspection Document #: 682404574

Weld County, CO

NWSE Section 12 T7N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DRAKE PAD
Location ID: 454899



Photo 1. Photo taken from the entrance of the location off HWY 14, facing North. Photo illustrates vehicle track device BMPs have been installed and appear to be in proper functioning condition.



Photo 2. Photo taken along the access road, facing West. Photo illustrates straw bales used as stabilized outlets along the culverts.

Inspection Photos
Location Name: DRAKE PAD
Location ID: 454899



Photo 3. Photo taken from the southeastern perimeter of the location, facing West. Photo illustrates two sets of ditch and berms.



Photo 4. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 3. Also, photo illustrates straw bales installed as check dams within the ditch BMP and rock is also used as check dams within the ditch BMP.

Inspection Photos
Location Name: DRAKE PAD
Location ID: 454899



Photo 5. Photo taken from the southwestern perimeter of the well pad, facing West. Photo illustrates the retention area.



Photo 6. Photo taken from the southwestern perimeter of the well pad, facing Northwest. See comments under Photo 5.

Inspection Photos
Location Name: DRAKE PAD
Location ID: 454899



Photo 7. Photo taken from the southwestern perimeter of the location, facing West. Photo illustrates the stabilized outlet from the retention area. Erosion control blankets have been installed along portions of fill slopes.



Photo 8. Photo taken from the southwestern perimeter of the location, facing East. See comments under Photo 7.

Inspection Photos
Location Name: DRAKE PAD
Location ID: 454899



Photo 9. Photo taken from the southwestern perimeter of the location, facing North. See comments under Photo 7.



Photo 10. Photo taken from the northern perimeter of the well pad, facing East. Operator shall stabilize cut slopes.



Photo 11. Photo taken from the southern well pad, facing South. Photo illustrates the topsoil stockpile which has been temporarily stabilized with equipment tracking.